Work Ord April 27, 2010		182										Page
Item ID: Revision ID: Item Name:	D3566-1 Gasket			Accept				s s	Setup Sta			
Start Date: Required Date Reference:	27/04/2010 : 04/05/2010	Start Qty: 16.0 Req'd Qty: 16.0		•••	Cust Item I Customer:	D:					1 1882/18/ 81	
Approvals:	Process Pla	nn:	Date:////-2/	Tooling: SPC (Y/N):		ite:		F	Run Sta St	art op		
Sequence ID/ Work Center I	D	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty		eject umber	Insp. Stamp
Draw Nbr	Rev	vision Nbr										
D3566	Rev	'C										
Waterjet FLOW CNC Water	jet	FLOW WATER JET Memo 1-Cut as Deburr	s per Dwg D3566 □Dwg Rev if necessary	0.00 0.00 v:□Prog Rev:_ _	□2-	`			0-4-	· >	<u> </u>	
110 QC Quality Control		QC2- Inspect parts o	ff machine FAI/FAIB	0.00				Bu	s- 4- ?	<u> </u>	(9))
120 		QC8- Inspect parts -	second check	0.00 Z 1060	edr			wester Cost) 	· 		

Memo

Quality Control

Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:				WOR	K ORDER CHANG	SES					
DATE	STEP	P	ROCEDURE	CHANG	E	I	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										İ	
								Ì			
1			:						İ	!	
								i			
							11			, , , , , , , , , , , , , , , , , , , ,	
Part No		PAR #:									
	R	esolution:	Dispo	sition: _		QA: N	/¢ Cl	osed:		Date:	
NCR:			WORK C	RDER	NON-CONFORM	ANCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section B				Verification		Approval	Approval
		Section A	Initia Chief Er		Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
			1								
			i					i			
								'			
	:							:			
			· · · · · · · · · · · · · · · · · · ·					1			
										İ	
<u> </u>			1								

Work Order ID 5818	Work	Order	ID	58182
--------------------	------	-------	----	-------

April 27, 2010 1:42:41 PM



Page 2

Item ID:

Revision ID: Item Name:

D3566-1

Gasket

27/04/2010

Accept

Setup Start



Required Date: 04/05/2010

Start Qty: 16.00 Req'd Qty: 16.00

Cust Item ID:

Customer:

Reference: Approvals:

Start Date:

Process Plan: _____ Date: ___

Tooling:

Date:

Run

Start

Stop



QC: Date:_____

SPC (Y/N):

Set Up/

Date:

Stop

Sequence ID/ **Work Center ID**

130

Packaging Packaging

Operation Description

Identify as per dwg & Stock Location

Memo

Memo

Run Hours

0.00

0.00

Draw Number

Draw Rev.

Plan Code

Accept Qty Qty

Reject Reject

Insp. Number Stamp

10-4.78

1500

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

10/04/29 A) BS10-41-29

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:		,	W	ORK ORDER CHANG	ES	i		
DATE	STEP	PRO	OCEDURE CH		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							Prod Wgr	
		,					}	
							•	
Part No	•	PAR #:	Fault Cat	egory:	NCR: Yes	No DQA:	Date: _	
	Re	esolution:	Dispositi	on:	_ QA: N/C CI	osed: _i	Date: _	
NCR:				DER NON-CONFORMA				···
DATE	STEP	Description of NC		Corrective Action Section		Verification	Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector
•		,						
						·		
		·						
· · · · · · · · · · · · · · · · · · ·								
		\ 						·
	1					i		
							į	
NOTE 5	1 0 : :::							

Work Order ID: 58182

Parent Item:

D3566-1

Parent Item Name:

Comments:

Gasket

IPP Rev:A

IPP Rev:B

New Issue 07-03-08 ec Added Drain Holes 07-07-09 JLM

IPP Rev:C

As per Rev C 07-09-09 JLM Verified By:EC

Start Date: 27/04/2010

Required Date: 04/05/2010

Required Qty: 16.00

Component Item ID/

MNEO60S.063

Replacement Mfg/

Purchased

Bin Primary No

Last

Route 100

Unit of sf

Qty on

Remaining 258.7531 15.3432 36.2

Start Qty: 16.00

Qty

Date

1810-4-27

Status

NEOPRENE SHEET 0.063

Warehouse

Location

Main Warehouse MAT052

114176

Loc Oty

Loc Code

258.7531

258.7531

114176

V/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
		!										
		,			····							

Part No:		PAR #:	Fault Category:	NCR: Y	es No	DQA:	Date:
F	Resolution:		Disposition:	QA: N/C	Closed	•	Date:

	WORK ORDER NON-CONFORMANCE (NCR)										
0777	Description of NC		Corrective Action Section B	Varification	Annroyal	Approval					
SIEP	Section A	Initial Chief Eng	InitialAction DescriptionSign &Chief EngChief EngDate		Sign & Section C Chief Er		Approval QC Inspector				
						·					
					,						
	:										
	!										
	STEP	STEP Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Action Description	STEP Description of NC Section A Initial Action Description Sign &	STEP Section A Initial Action Description Sign & Verification Section C	STEP Description of NC Section A Initial Action Description Sign & Section C Chief English				

DART AEROSPACE LTD	Work Order:	58182
Description: Gasket	Part Number:	D3566-1
Inspection Dwg: D3566 Rev: C		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.10	+/-0.030	3,092	8			
18.00	+/-0.030	19.60	2			
12.10	+/-0.030	17.100	>			
2.43	+/-0.030	7,429	N N			
6.00	+/-0.030	6.000	>			
1.40	+/-0.030	1.409	×			
0.30	+/-0.030	.306	×			
0.30	+/-0.030	363	>			
0.063	+/-0.010	.663	y	-		
Ø0.188	+0.005/-0.001	,191	7			


Measured by:		Audited by:	5	Prototype Approval:	N/A
Date: (ひ-	-4-57	Date:	scholor	Date:	N/A

Rev	Date	Change	Revised by	A
Δ	07.03.14	New Issue	Revised by	Approved
<u> </u>			KJ/JLM	
l B i	07.07.18	Dimensions updated per Dwg Rev. B	KJ/JLM	
		Dwg Rev updated		
	07.03.20	Dwg Nev updated	KJ/EC/DD	12

Part Aerospace Ltd						•	
V/O:		WORK ORDER CH	IANGES				-
DATE	STEP	 PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					-		1

Part No:	lo: PAR #		Fault Category:		NCR: Yes No DQA:		Date:	
	Resolution:		Disposition:		QA: N/C Closed		Date:	
		\\/C	DE ODDED NON COM	VICODRA A B	ICE (NCD)		*	

							*
	TEP Description of NC Section A		Varification				
STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector
	1						
		7.7	•				
	i						
	·						
	TEP	Description of NC Section A	Section A Initial	Section A Initial Action Description	Section A Initial Action Description Sign &	Section A Initial Action Description Sign & Verification Section C	Section A Initial Action Description Sign & Verification Approval



Dart Aerospace Ltd W/O: WORK ORDER CHANGES DATE STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr

Part No:		PAR #:	Fault Category:	NCR: \	∕es No DQA:	Date:
	Resolution:		Disposition:	QA: N/	C Closed:	Date:
NCR:			WORK ORDER NON-CON	FORMANCE (N	ICR)	
			Corrective Action	D Castian D		

Approval QC Inspector

							···	
DATE	STEP	Description of NC	Corrective Action Section B			Verification	Approval	Annroyal
DAIL		SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng
						ļ ļ		
						1		
						1		
		i	·					
		i						
								
					1	1		
								,
								 -
				1		1	1	1